


## CHALUTIER "RYSTRAUM" – NORVÈGE

L'application du **ZINGA** sur le chalutier « Rystraum » a eu lieu en 1984.

Ce navire est un chalutier de 115 pieds et opère dans la mer Barents. Lors de la première inspection, 9 mois après application, il s'avérait qu'il y avait quelques algues sur sa coque.

Ces algues ont ensuite été éliminées avec de l'eau à haute pression. La couche de **ZINGA** n'était pas endommagée. Lors d'une inspection en 1986 il n'y avait plus de traces d'algues.

Ni de dommages particuliers pas même à la proue, malgré que ce chalutier ait été utilisé dans les mers arctiques.



ROTORKONTROLL A/S  
Teknisk/Kjemisk  
POB 31  
N-2014 BLYSTADLIA  
Phone: 47 63838724  
Fax.: 47 63838724  
Date 25.01.96

### Report M/S "RYSTRAUM", Tromsø Use of ZINGA on hull.

This report is based on a phonecall with the owner Sigurd Svendsen.

M/S "RYSTRAUM" is a 115 feet trawler operating in the Barents Sea.

The application of ZINGA took place in 1984.

The total layer thickness was estimated to be 100 - 120 µ and estimated life time of the layer is 7 - 8 years.

The application was based on brush after high pressure sandwashing.

At the first inspection approx. 9 months after application it appeared that some algae has appeared on the surface. These algae were, however, removed by using water/high pressure. The ZINGA layer was not damaged.

At the inspection in 1986 it appeared that the surface was completely free of algae. No damages even in the front area was discovered, this in spite of the fact that the vessel is operating in arctic areas (ice etc.). The reason for this last inspection was electrical voltage in the hull. This reduced the zinc-anodes but not the ZINGA layer.


It was used normal zinc-anodes and it appeared that the lifetime of this anodes was extended.

The savings in this case are estimated as follows:

(NOK in 1984 value)

Saved material costs	NOK	12.000.-
Saved docking costs	NOK	150.000.-
Saved fuel consumption: 1 nm/h - 200 ltr/h	NOK	180.000.-

This report is translated 1996 and we can inform you that M/S "RYSTRAUM" is no longer operated by the owner Sigurd Svendsen.



Ceci est un rapport de Mr Hagen, consultant de l'ancien propriétaire, du 25-01-1996, décrivant l'état du **ZINGA** après une inspection en 1986 et donnant une estimation des économies faites sur la consommation de fioul, de frais de cale et de peintures antisalissures.

Système:  
**ZINGA 2 x 60 µm EFS**