

CEMENT SILOS – DANGOTE GREENVIEW – GHANA

This cement plant that is property of the **DANGOTE Group** has been protected with **ZINGA**. The high-quality solution that **ZINGA** is, has been chosen after the new plant (without **ZINGA**) started corroding after only 3 years.

Before it was decided to use **ZINGA**, it was applied on several critical areas and after a test period of 1 year (ending in 2007) the 'go ahead' for the complete Zingatisation was given.



Every steel part of the plant has been protected with **ZINGA**.

The application was finished begin 2009.



System:

ZINGA 2 x 60 µm DFT