

## CHIMNEY – SULTAM – ISRAEL

An old chimney in the factory **SULTAM** Ltd in Yokneam, Israel, was repaired and protected with **AQUAZINGA** in 1997, after internal combustion. It was originally electrolytically galvanised.



System:  
AQUAZINGA 2 x 60 µm DFT