

TANKS – NEW PLYMOUTH – NEW ZEALAND

In 2007, two tanks of the **New Plymouth Power station** in New Zealand were protected with **ZINGA**.

These tanks have to endure the sea mist of the New Plymouth coast, which is the cause of the high corrosion rate and the appearance of red rust on the old system.

ZINGA will do a much better job than the previous system providing peace of mind for the users.

Before application with **ZINGA**: visible rust spots.



About one month after application with **ZINGA**.



System:
decontamination by UHP cleaning
blasting to SA 2,5.
Zinga 2 x 90 µm DFT