


## Grain Silos & Flour Mills – AL ARABIYA – YEMEN

In 2015 the **Al-Arabiya Grain Silos** company requested the use of **ZINGA** as touch up of galvanized steel for their new project in **Hodeidah Port**, Republic of Yemen. They left the structures for 2 years in bad storage conditions causing white and red rust. The repair process was successful, and they used 1.5 tons of **ZINGA**. The surface was prepared using manual tools along using some chemical products for white rust removal and washing by fresh water. The **ZINGA** was applied by brushes and all patch repair work was done before erection.



2 years after application the ZINGA was covered under sand and the only visible damages were the result from manipulation and assembly.



System:

ZINGA

2 x 60 µm DFT